

DAILY FIELD REPORT

Supplemental PDI Investigation – OU3 Pohatcong Valley Groundwater Contamination Superfund Site Warren County, New Jersey

DATE: Tuesday, December 25, 2018

PREPARED BY: Michael Eddings/Stam Popelar

RAMBOLL ON-SITE: Mike Eddings, Nita Shinn, and Jay Shipley

SUBCONTRACTORS ON-SITE: Cascade Drilling (Ben Grim, Marshall Daniels, Dennis Schweisthal, Kevin Smith, Jon Weeks, Oiden Gonzales, Kendall Schultz)

VISITORS: USACE (None)

WEATHER: Low 27°F, high 40°F, partly sunny.

ACTIVITIES PERFORMED THROUGH 7PM (END OF FIRST SHIFT)

- Rigs are positioned at PDI-SB27 and PDI-SB28.
- Enclosures have been completed at both locations.
- Hand clearing has been completed at both locations.
- Samples from 2.00 to 2.50 ft bgs from both locations were collected.

HSEQ ACTIVITIES/OBSERVATIONS (hazards, near misses, incidents or safety considerations)

- CRM/HSEQ Tailgate Safety Meeting was held at the on-site job trailer for all onsite personnel at the Albéa facility at 191 Hwy 31 N, Washington, NJ.

SAMPLE COLLECTION ACTIVITIES:

- Samples Collected: POH-PDI-SB27(2.00-2.50), POH-PDI-SB28(2.00-2.50).

PROBLEMS, CONCERNS AND RESOLUTIONS:

- None.

ANTICIPATED TASKS THROUGH Wednesday, December 26, 2018:

- Installation of noise and vibration monitoring equipment before drilling begins.
- Complete walk around each drilling area for final confirmation check prior to drilling.
- Begin drilling at both locations.

PHOTOGRAPH(S) ATTACHED? ☒ YES ☐ NO





